BHOME		HARDWARE LIST				
ASSEMBLY INSTRUCTION		DES	DESCRIPTION		QTY	
MODEL SLIP LEAF TABLE		JCBC SCREW M8 x 60MM		8 PCS		
		SPRING WASHER M8 x 12 x 2.0M		8 PCS		
	С	FLAT WASHER M8 x 22 x	1.0M	0	8 PCS	
Assembly Tips	D	ALLEN KEY M5			1 PC	
Remove hardware from box and sort by size. PART LIST						
2. Please check to see that all hardware and parts are present prior start of assembly.					QTY	
3. Please follow attached instruction in the same see	quence	uence as numbered to assure		TABLE TOP	1 PC	
fast and easy assembly. 1 TABLE TOP 2 TABLE LEG					4 PCS	
IMPORTANT NOTE : 1. Place all wooden parts in a clean and smooth surface such as a rug or carpet to						
avoid the parts from being scratched.						
2. Before you being, kindly follow the assembly instruction step by step.						
Before you being, kindly follow the assembly instruction step by step.					IJ	
3. Do not tighten all screw until the product is fully set-up.						
			CAUTION!			
STEP 1	STEP 2		Please lift the switch to unlock the extension mechanism before extending or closing the extension table.			
				Once the table has been closed or		
	——————————————————————————————————————		extended, please flip the switch to lock the extension mechanism from further			
			movement during usage.			
			Please ensure the table is properly aligned before locking the mechanism			
			LO			
			R	\rightarrow		
)) [0_		
	0-				J	
STEP 3		EP 4				
Pull one side table of the table top either left or right. This is to avoid the damage caused by the two sides						
pulling.						
						
					•	

Complete Assembly